



Sub - Handing over of maintenance for electrical work at
various Ugran from ED-6 to ED-LD-13

Above site Rosebeam checked out 05.06.21, 07.06.21
and 08.06.21. All the lights in neon strip is not functional
and Rosebeam got damaged badly although the neon strip
lights are in guarantee period of 5 years. It is
also informed you that ^{all} C.C. TV cameras in the park
are not functional. only 4 No CCTV cameras were
working. When I was inform/ talk to Agency of
C.C. TV camera m/s. Sagjeet he ask me that the cables
of cameras are get damaged and it is not comes
in my scope of maintenance. It is also observed
that control cable of camera is not laid ~~back~~ as per
specifications. it is laid about 5" to 6" below the
ground in PVC pipe and the pipes are not jointed
properly. In this position this position this office
is unable to maintain the C.C. TV cameras and
Neon strip lights. because as discuss by AE/ED-6
Arun Kumar these are under the guarantee period
but the agency is not ready ^{and agree} to maintain and of
above said cameras and lights. Because this office
has not any power to ask the agency to do
any thing

AE/ED-13

Recd/Retd
09/06/2021
JE(E)/ED-13

It is requested to issue the instructions to ED-6 and
these AE & JE will also handover the completion plan of
lighting arrangement so that lights can be maintain by
this office properly submitted for further instructions

ED-13

Recd/Retd
09/06/2021
AED/ED-13

दिल्ली विकास प्राधिकरण

P.T.O

Issue of GRS with SE(E) South
zone on dt 11/6/21 and assured
to hand over the layout plan.
for Complete Installation of
Hand over the Installation

Page
11/6/21

✓ AELEJPR